
































Návod na sestavení

- | | | | | | | | | | | |
|---|---|-----------|------|---|---|---------|-----|---|---|-----|
| ① |  | Ø3.5 x 50 | x 28 | ⑤ |  | M6 x 55 | x 4 | ⑧ |  | x 1 |
| ② |  | Ø3.5 x 35 | x 5 | ⑥ |  | M6 x 25 | x 4 | | | |
| ③ |  | Ø3.5 x 25 | x 8 | ⑦ |  | Ø7 x 18 | x 4 | | | |
| ④ |  | Ø3, 16 | x 10 | | | | | | | |

 A	 B	 C x 2	 D	 E
 F	 G	 H	 I	 J
 K	 L	 M	 N	 O
 P	 Q	 R	 S	 T
 U	 V	 Z		

Návod na sestavení

1

C
B
D

① — $\varnothing 3.5 \times 50$ x12
② — $\varnothing 3.5 \times 35$ x1

2

H
E
G

F

③ — $\varnothing 3.5 \times 50$ x10

3

④ — $\varnothing 3.5 \times 50$ x6

4

L
M
N
O

⑤ — $\varnothing 3.5 \times 35$ x4
⑥ — M6 x 55 x4

5

T

K

6

P

R

S

⑦ — $\varnothing 3 \times 16$ x4
⑧ — M6 x 25 x4
⑨ — $\varnothing 7 \times 18$ x4

7

U
V

I

Z

⑩ — $\varnothing 3.5 \times 25$ x8

8

⑪ — $\varnothing 3 \times 16$ x6