


































MONTÁŽNÍ NÁVOD


			5		1ks
			6		1ks
1		1ks	7		1ks
2		1ks	8		1ks
3		1ks	9		1ks
4		1ks	10		1ks
			11		1ks
			12		1ks

13		1ks	18		1ks
14		1ks	19		1ks
15		1ks	20		1ks
16		1ks	21		2ks
17		1ks	A	 Ø6*45	4ks
A	 Ø6*45	4ks	D	 3*25	8ks
B	 3.5*60	4ks	E	 3*16	8ks
B	 3.5*60	4ks	F		1ks
C	 3.5*35	34ks			


1




2





3





4





5




6




7



8



9



10

